




# USAG ANSBACH



## Local Driving Hazards In the USAG Ansbach Footprint



## B-13 Between Ansbach and Illesheim

- North of Oberdachstetten there is a steep decline that goes under a railroad overpass.
- One lane of traffic going down the hill and two lanes of traffic going down the hill.



**DO NOT PASS**



# USAG ANSBACH



## B-13 Between Ansbach and Illesheim



There has been fatalities because of excessive speed and icy conditions that have caused personnel to lose control of the car.



# USAG ANSBACH



## B-13 Between Ansbach and Illesheim



Vehicles pick up excessive speed going down the hill and around the curve; farm vehicles enter B13 very slowly  
Resulting in impact!



# USAG ANSBACH



## B-13 Between Ansbach and Illesheim



Coming from Illesheim driving up the steep incline  
toward Oberdachstetten

The shades allows frost and black ice to stay  
on the road longer.






# USAG ANSBACH



## B-14 Between Wicklesgreuth and Ansbach



This is a supplemental  
Sign warning:

Unexpected ice

Due to forest areas  
several fatalities have occurred here! both sides of the road.



# USAG ANSBACH



## B-14 from Katterbach into Ansbach



Speed drops from  
100 Km  
80 Km  
50 Km  
Very quickly

Many tickets  
have been issued  
here